





<p>RU</p>	<p>Кольцо для троса овальное 5мм</p>	 <p>31023</p> <p>15x17x12 mm 0,01 kg/pc</p>
-----------	--------------------------------------	--

<p>RU</p>	<p>Кольцо для троса</p>	 <p>31025</p> <p>18x8 mm 0,01 kg/pc</p>
-----------	-------------------------	---

<p>RU</p>	<p>Трос стальной в сборе:</p> <table data-bbox="319 1321 877 1568"> <tr> <td>90031</td> <td>D = 3 mm</td> <td>2 x 3000 mm</td> </tr> <tr> <td>90041</td> <td>D = 3 mm</td> <td>2 x 4000 mm</td> </tr> <tr> <td>90051</td> <td>D = 3 mm</td> <td>2 x 5000 mm</td> </tr> <tr> <td>90061</td> <td>D = 3 mm</td> <td>2 x 6000 mm</td> </tr> <tr> <td>90071</td> <td>D = 3 mm</td> <td>2 x 7000 mm</td> </tr> <tr> <td>90081</td> <td>D = 3 mm</td> <td>2 x 8000 mm</td> </tr> <tr> <td>90091</td> <td>D = 3 mm</td> <td>2 x 9000 mm</td> </tr> <tr> <td>90101</td> <td>D = 3 mm</td> <td>2 x 10000 mm</td> </tr> </table>	90031	D = 3 mm	2 x 3000 mm	90041	D = 3 mm	2 x 4000 mm	90051	D = 3 mm	2 x 5000 mm	90061	D = 3 mm	2 x 6000 mm	90071	D = 3 mm	2 x 7000 mm	90081	D = 3 mm	2 x 8000 mm	90091	D = 3 mm	2 x 9000 mm	90101	D = 3 mm	2 x 10000 mm	 <p>90**1</p> <p>6x19 mm+pp 0,05 kg/m</p>
90031	D = 3 mm	2 x 3000 mm																								
90041	D = 3 mm	2 x 4000 mm																								
90051	D = 3 mm	2 x 5000 mm																								
90061	D = 3 mm	2 x 6000 mm																								
90071	D = 3 mm	2 x 7000 mm																								
90081	D = 3 mm	2 x 8000 mm																								
90091	D = 3 mm	2 x 9000 mm																								
90101	D = 3 mm	2 x 10000 mm																								

<p>RU</p>	<p>Трос стальной в сборе:</p> <table data-bbox="319 1780 877 2072"> <tr> <td>90032</td> <td>D = 4 mm</td> <td>2 x 3000 mm</td> </tr> <tr> <td>90042</td> <td>D = 4 mm</td> <td>2 x 4000 mm</td> </tr> <tr> <td>90052</td> <td>D = 4 mm</td> <td>2 x 5000 mm</td> </tr> <tr> <td>90062</td> <td>D = 4 mm</td> <td>2 x 6000 mm</td> </tr> <tr> <td>90072</td> <td>D = 4 mm</td> <td>2 x 7000 mm</td> </tr> <tr> <td>90082</td> <td>D = 4 mm</td> <td>2 x 8000 mm</td> </tr> <tr> <td>90092</td> <td>D = 4 mm</td> <td>2 x 9000 mm</td> </tr> <tr> <td>90102</td> <td>D = 4 mm</td> <td>2 x 10000 mm</td> </tr> <tr> <td>90112</td> <td>D = 4 mm</td> <td>2 x 11000 mm</td> </tr> <tr> <td>90122</td> <td>D = 4 mm</td> <td>2 x 12000 mm</td> </tr> </table>	90032	D = 4 mm	2 x 3000 mm	90042	D = 4 mm	2 x 4000 mm	90052	D = 4 mm	2 x 5000 mm	90062	D = 4 mm	2 x 6000 mm	90072	D = 4 mm	2 x 7000 mm	90082	D = 4 mm	2 x 8000 mm	90092	D = 4 mm	2 x 9000 mm	90102	D = 4 mm	2 x 10000 mm	90112	D = 4 mm	2 x 11000 mm	90122	D = 4 mm	2 x 12000 mm	 <p>90**2</p> <p>6x19 mm+pp 0,10 kg/m</p>
90032	D = 4 mm	2 x 3000 mm																														
90042	D = 4 mm	2 x 4000 mm																														
90052	D = 4 mm	2 x 5000 mm																														
90062	D = 4 mm	2 x 6000 mm																														
90072	D = 4 mm	2 x 7000 mm																														
90082	D = 4 mm	2 x 8000 mm																														
90092	D = 4 mm	2 x 9000 mm																														
90102	D = 4 mm	2 x 10000 mm																														
90112	D = 4 mm	2 x 11000 mm																														
90122	D = 4 mm	2 x 12000 mm																														